


CORNER RECORDDocument Number 712City of OAKLANDCounty of ALAMEDA, CaliforniaBrief Legal Description LOT 91, CLAREMONT KNOLLS SUBDIVISION OF THE TAYLOR PROPERTY,
BLOCK L, (10M98).**CORNER TYPE****COORDINATES**
(Optional)

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey JANUARY 3, 1992

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SET 4 LOT CORNERS LOT 91 FROM MONUMENTS AS SHOWN ON MAP OF "CLAREMONT KNOLLS, SUBDIVISION OF THE TAYLOR PROPERTY, BLOCK 'L' ". OAKLAND, ALAMEDA COUNTY, CALIFORNIA. FILED 1/18/27 BOOK 10 MAPS, PAGE 98. LOT 91 IS ALSO PARCEL "D", PARCEL MAP 1914, MAP BOOK 91, PAGE 19, FILED 6/30/76, ALAMEDA CO. RECORDS.

A description of the physical condition of the monument as found and as set or reset: _____

1/2" x 30" REBAR WITH PLASTIC CAP RCE 12104.
 SEE SKETCH ON PAGE 2 OF 2.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on JULY 13, 19 92.


Signed Theodore V. Tronoff R.C.E. Number 12104
 Exp. 6/31/97

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-20-1996 and examined

and filed 7-16-1996

Signed Russell R. Penland Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

